



# VOLUNTARY SAFETY RECALL

PIEPS AND BLACK DIAMOND announce Voluntary Recall of PIEPS Pro BT, Powder BT, DSP Sport, DSP Pro, DSP Pro Ice, Micro Button BT, Micro BT Sensor and Micro BT Race avalanche transceivers and the Black Diamond branded Recon BT and Guide BT avalanche transceivers



## RECALLED PRODUCT:

Avalanche transceivers including: PIEPS Pro BT, Powder BT, DSP Sport, DSP Pro, DSP Pro Ice, Micro Button BT, Micro BT Sensor and Micro BT Race avalanche transceivers and the Black Diamond branded Recon BT and Guide BT avalanche transceivers

## HAZARD:

The recalled transceivers may not be able to switch from SEND mode into SEARCH mode. If this were to occur, the device would not be able to locate another skier in an avalanche, which could result in severe bodily harm or death if a skier is buried under snow.

## REMEDY: Replace, Repair

Consumers should immediately stop using the recalled transceivers and perform a safety check to verify if the device can switch into Search Mode by following instructions found on the Black Diamond website.

## CONTACT:

PHONE: 866-306-0865 from 9 a.m. to 4 p.m. MT Monday – Friday

EMAIL: [2022beaconrecall@bdel.com](mailto:2022beaconrecall@bdel.com)



Product recalls can be found here.