

SAFETY RECALL

YETI Recalls Soft Coolers and Gear Case Due to Magnet Ingestion Hazard



The magnet-lined closures of the Hopper M20 Soft Backpack Cooler, the Hopper M30 Soft Cooler (both the 1.0 and 2.0 versions) and the SideKick Dry Gear Case can fail and result in detached magnets, which poses a risk of serious injury or death if ingested.



Hopper M30 1.0



Hopper M30 2.0



Hopper M20



SideKick Dry

Sold between March 2018 and January 2023 for \$325 (Hopper M20 Soft Backpack Cooler), \$300 (Hopper 1.0 Soft Cooler); \$350 (Hopper 2.0 M30 Soft Cooler) and \$50 (SideKick Dry Gear Case).

Consumers should immediately stop using the recalled products listed above, visit www.yeti.com and click on "Product Recall" at the bottom of the page for information on how to return the recalled product for a free replacement or gift card as shown below:

- Sidekick Dry: \$50 MRP
 - Daytrip Bag/Box (\$80 MRP) OR \$75 Gift Card
- M20: \$325 MAP
 - Tundra 45 (\$325 MRP) + \$50 Gift Card OR \$350 Gift Card
- M30 1.0: \$300 MAP
 - Flip 18 (\$300 MRP) + \$50 Gift Card OR \$325 Gift Card
- M30 2.0: \$350 MAP
 - Tundra 65 (\$375 MRP) + \$50 Gift Card OR \$375 Gift Card

Customers can also contact YETI toll-free at 1-833-444-3151 from 7:00 AM to 7:00 PM CT, or email ProductRecall@yeti.com for more information.