

# RECALL NOTICE

## PNW COMPONENTS RECALLS LOAM GEN 2 PEDALS



**HAZARD:** The pedal axle can crack, causing the pedal to detach from the crank, posing a fall hazard to the rider.

**RECALLED PRODUCT:** This recall involves the PNW Components Loam Pedal Gen 2 aluminum alloy mountain bike pedal. These pedals were sold after market through online retailers and bike shops. The pedal is a platform style (non-clip) pedal and can be identified by a “Tectonic” logo laser etched onto the pedal body on the left corner, on the same side as the threaded axle. The pedals are available in black, silver, green, orange, and purple.

**REMEDY:** Consumers should immediately stop using the Loam Pedal Gen 2 and contact PNW components to receive free replacement axles and instructions on replacement.

### FOR MORE INFORMATION

**1-833-902-3381**  
**[info@pnwcomponents.com](mailto:info@pnwcomponents.com)**

*Monday through Friday 8:00 a.m. to 4:00 p.m. PST*



This recall is being conducted in cooperation with the U.S. Consumer Product Safety  
Commission.

Post Until May 21, 2026