

Recall Date: 30 December 2022

SCARPA North America Recalls Certain Production Batches of Fall 2022 F1 LT and F1 GT Ski Boots

Recall Summary

Name of Product: F1 LT and F1 GT Ski Boots (both men's and women's).

Hazard: In some of the boots manufactured in Fall 2022, the two screws attaching the ski/walk mechanism to the cuff may not be securely connected. If the screws loosen or fall out, the ski/walk mechanism may not function properly posing the risk of a fall.

Remedy: Repair. Replacement of two screws on each boot that attach the ski/walk mechanisms to the cuffs. Consumers should immediately stop using the boots contact SCARPA for instructions on replacing the screws.

Consumer Contact: SCARPA North America toll-free at (866) 998-2895 from 8 a.m. to 5 p.m. MT Monday through Friday or online at www.us.scarpa.com and click on the link marked "F1 LT & GT RECALL" for more information.

Recall Details

Description: This recall applies only to certain production batches of Fall 2022 F1 LT and F1 GT ski boots (men's and women's). The recall does NOT apply to F1 LT and F1 GT boots manufactured in 2019, 2020 or 2021. Boots that were purchased before August 1, 2022 are NOT affected by this issue. The F1 LT boots were sold in Carbon /Orange for men and Carbon/Aqua blue for women with "SCARPA" written in white letters on the lower outer side of the boot. The F1 GT boots were sold in Petrol/Orange for men and Petrol/Aqua for women, with "SCARPA" written in white letters on the lower outer side of the boot. The model name "F1 LT " or "F1 GT" is printed on the upper right outside ankle cuff of the boots.

For information on how to identify the boots subject to the recall, please see the detailed description below.

Sold at: Authorized SCARPA dealers and retailers in the United States and Canada, including Backcountry.com, REI and Skimo Co., and online at www.us.scarpa.com from August 2022 through December 2022 for about \$700.

If your boots are subject to the recall, or if you have any questions about whether your boots are subject to the recall, **please contact SCARPA immediately, toll-free at (866) 998-2895 from 8 a.m. to 5 p.m. MT Monday through Friday or email us at: recall@scarpa.com** to remedy the issue.

Photos



Men's and Women's F1 LT ski boots; Men's and Women's F1 GT ski boots

How to Identify Boots Subject to the Recall

To identify boots manufactured in 2022 and purchased after August 1, 2022, that are subject to the recall, please follow the steps below.

A. If you have the original box:

Check the production batch number located on the box label, which can be found on the label in the area indicated below with the red square:



1. If the production batch number ends in any of the eight 6-digit numbers below, then the screws **MUST** be replaced. If the production batch number ends in any other number, the boots are **NOT** subject to this recall.

DISTRIBUTOR	Batch	Style #	Description
SCARPA N.A.	600014	12182-501/1	F1 GT PETROL-ORANGE
SCARPA N.A.	600040	12182-501/1	F1 GT PETROL-ORANGE
SCARPA N.A.	600013	12182-502/1	F1 GT WMN PETROL-AQUA
SCARPA N.A.	600039	12182-502/1	F1 GT WMN PETROL-AQUA
SCARPA N.A.	600010	12172-500/1	F1 LT CARBON-ORANGE
SCARPA N.A.	600042	12172-500/1	F1 LT CARBON-ORANGE
SCARPA N.A.	600018	12172-502/1	F1 LT WMN CARBON-AQUA
SCARPA N.A.	600041	12172-502/1	F1 LT WMN CARBON-AQUA

B. If you do NOT have the original box:

1. Place the Ski/Walk mechanism in “walk” mode.
2. Push cuff back as shown in image 1 below.
3. Locate year of manufacture stamp molded into the cuff and shown in image 2.
4. If the molded arrow points to 2019, 2020 or 2021 then they are NOT affected by this issue, and screw replacement is NOT necessary.
5. If the arrow points to 2022, then they may be affected by this issue and the screws should be replaced.

